



# INFORMATION BULLETIN




## NAT Part No.: NTX138

**COBHAM**  
Published on  
10 February 2016

These commodities, technology or software are Controlled in accordance with the United States Export Administration Regulations. When exported from the United States, diversion contrary to U.S. Law is prohibited.

Description: **Intermittent Failure to Receive**  
Information Bulletin #: **609-0**

Document #: **SM28\Bulletins\609-0001**

Prepared By:		Checked By:		Approved By:	
--------------	---	-------------	---	--------------	---

### 1. **Applicability**

This information is applicable to the following:

NTX066-001 s/n 1129 – 1130  
NTX066-002 s/n 1020 – 1023  
NTX138-000 s/n 1552  
NTX138-001 s/n 1551  
NTX138-003 s/n 1021 – 1022  
NTX138-100 s/n 1545 – 1550

### 2. **Subject**

NTX units may experience intermittent failure to receive especially on higher frequencies as there is a possibility the unit may contain an out of specification oscillator.

### 3. **Action**

NTX units experiencing intermittent failure to receive, especially on higher frequencies, should be returned for service.

#### 3.1 **Costing**

This upgrade is not subject to warranty consideration. Please contact Northern Airborne Technology Ltd. Product Support for service information.

End of information bulletin