



INFORMATION BULLETIN

NAT Part #: NPX136D-070
Description: P25 VHF Panel Mount Transceiver

Information Bulletin #: 001
Document #: SM68\609-0001

Prepared By:		Checked By:				Approved By:	
--------------	--	-------------	--	--	--	--------------	--

1. Applicability

1.1 This information is applicable to all NPX136D-070 s/n 1020 and below.

2. Subject

2.1 The initialization sequence for the transceiver module does not always occur, resulting in erratic scanning operation.

2.2 The display does not indicate the radio's operating frequency to 0.5 kHz (the fourth digit past the decimal point).

2.3 The customer has requested different tones/codes for RX and TX in simplex operation.

2.4 GD TX does not transmit proper modulation type and NAC/Tone/Code.

3. Recommendation

3.1 The implementation of these changes is the customer's option and can only be accomplished at the factory.

3.2 These changes are accomplished by loading firmware version 1.03.04 or later.

End of information bulletin