

REV C	APPLICATION			REVISIONS			
	NEXT ASSEMBLY	FINAL ASSEMBLY	REV	DESCRIPTION	DATE	APPROVED	APPROVED
SH 1		DM-441B	A	INITIAL RELEASE PER DCN W4692	08/25/05	V. Wallace	C. Estes
			B	Revised per DCN W4706	09/08/05	V. Wallace	C. Estes
			C	Revised per DCN W4961	02/08/06	V. Wallace	C. Estes

DWG. NO. 150-042240

THIS COVER SHEET IS FOR WULFSBERG ELECTRONICS DIVISION INTERNAL USE. IT IS NOT TO BE PUBLISHED WITH THE DOCUMENT IT DESCRIBES

THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF WULFSBERG ELECTRONICS DIVISION, A CHELTON GROUP COMPANY. NEITHER RECEIPT NOR POSSESSION THEREOF CONFERS ANY RIGHT TO REPRODUCE, OR USE, OR DISCLOSE, IN WHOLE OR IN PART, ANY SUCH INFORMATION WITHOUT WRITTEN AUTHORIZATION FROM WULFSBERG ELECTRONICS DIVISION.



Wulfsberg Electronics
A Chelton Group Company

APPROVALS	DATE	TITLE				
DRAWN L. Evans	08/22/05	SERVICE NOTIFICATION WSN DM-441B-08 (DME CPU Board Replacement)				
CHECKED C. Estes	08/22/05					
ENGINEER C. Estes	08/25/05	SIZE A	CAGE CODE 1B7G3	DWG. NO. 150-042240	REV C	
ISSUED V. Wallace	08/25/05	SCALE NONE				



SERVICE NOTIFICATION

EQUIPMENT: DM-441B

DATE: 02/08/06

BULLETIN NUMBER: WSN DM-441B-08 Revision C

APPLICABILITY

All units returned to Wulfsberg Repair facilities in Prescott, Arizona will be evaluated to determine if they are subject to compliance with this Service Notification. Upon completion of the evaluation a Service Notification compliance sticker shall be applied to all units addressed by the Service Notification.

This Service Notification applies to DM-441B LRUs as listed below:

Group A: LRUs identified that may contain CPU board P/N 200-08974-0033 with a printed circuit board problem that may allow DME intermittent operation:

SNs

38289	38829	39385	39710	39998
38489	38831	39386	39711	39999
38541	39121	39387	39712	40000
38542	39122	39428	39713	40001
38543	39123	39429	39714	40118
38546	39124	39431	39793	40150
38548	39127	39432	39818	40151
38549	39128	39433	39819	40153
38551	39129	39435	39826	
38552	39161	39436	39827	
38553	39382	39437	39828	
38554	39126	39541	39829	
38555	39147	39542	39955	
38556	39273	39543	39956	
38558	39274	39548	39957	
38559	39275	39549	39958	
38561	39376	39572	39959	
38562	39377	39574	39995	
38563	39383	39575	39996	
38564	39384	39708	39997	

Group B: LRUs that Wulfsberg has already verified not to contain the suspected problem CPU board or that have had the problem CPU board P/N 200-08974-0033 replaced. This group still requires the application of a sticker to identify compliance to this Service Notification:

SNs

38484
38545
38560
38830
39120

Group C: LRUs that Wulfsberg Repair Facility has in process, that will be identified with this Service Notification compliance as completed prior to Return to Service:

SNs

38075
38565
38828
39130

INSTRUCTIONS:

All compliance activities involved with this Service Notification will be accomplished at the Factory Wulfsberg Repair Station facility in Prescott, AZ U.S.A.

Customers that identify that they have SNs in Group A should coordinate the return of the LRUs so identified, through Wulfsberg Repair Station, Prescott, AZ Phone: (928) 708-1531 Fax: (928) 708-1532 or Email: service@wulfsberg.com.

Customers that identify that they have SNs in Group B should request a compliance sticker for this Service Notification from Wulfsberg Repair Station, Prescott, AZ Phone: (928) 708-1531 Fax: (928) 708-1532 or Email: service@wulfsberg.com.

Group C SNs are to be identified with the compliance sticker prior to being Returned to Service by the Wulfsberg Repair Station.

Compliance Sticker p/n 156-041165-02, quantity 1. See Figure 1 for placement of sticker.

Compliance sticker



Figure 1