


REV	APPLICATION			REVISIONS		
	PRODUCT LINE	REV	DESCRIPTION	DATE	APPROVED	APPROVED
SH	C-5000	A	Initial Release per DCA W7527	9/11/08	Jay Jensen	Linda Andujo
DWG. NO. 150-042563-19						

THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF WULFSBERG ELECTRONICS, A CHELTON GROUP COMPANY, NEITHER RECEIPT NOR POSSESSION THEREOF CONFERS ANY RIGHT TO REPRODUCE OR USE, OR DISCLOSE, IN WHOLE OR IN PART, ANY SUCH INFORMATION WITHOUT WRITTEN AUTHORIZATION FROM WULFSBERG ELECTRONICS

		 Wulfsberg Electronics <i>A Chelton Group Company</i>		
APPROVALS				DATE
DRAWN	Jay Jensen	9/10/08		TITLE: SERVICE NOTIFICATION WSN C-5000-19 Revert SWID 35-36 units with Internal CTCSS Tone Board to SWID 33
CHECKED	Jay Jensen	9/10/08		
PRODUCT MANAGER	-----			
ENGINEER	----			
ISSUE	Linda Andujo	9/11/08		SIZE A
		CAGE CODE 1B7G3	DWG NO. 150-042563-19	REV A
Typed signatures indicate approval. Handwritten signature approval of this document is on file at Wulfsberg Electronics, Prescott, Arizona.		SCALE: NONE		DO NOT SCALE DRAWING



Wulfsberg Electronics
A Chelton Group Company

SERVICE NOTIFICATION

EQUIPMENT: C-5000

DATE: 9/11/08

SERVICE NOTIFICATION NUMBER: WSN C-5000-19

Revision A

EFFECTIVITY

Effects PN's 31300-0x01-13xx, 31300-0x01-1x3x, and 31300-0x01-1xx3 and identified with SW ID 35 or 36.

REASON

Revert to SWID 33 to restore CTCSS receive tones functionality.

DESCRIPTION

Install SWID 33 in accordance with service bulletin WSB C-5000-9 (150-040495).

NOTE: Units identified with SWID 37 that have Serial RT control module(s) (P/N 300-016290-0302) must have the serial card removed or replaced with an older version that is compatible with SWID 33.

COMPLIANCE

Upon next scheduled maintenance.

APPROVAL

This modification does not affect the original approval.